

Information regarding the Play equipment in Glen Gardens. (Information provide by Paul Thompson of SBC)

I have checked with our play area team and can confirm that:

- The roundabout has been removed because there was excessive play on the spindle. This had become badly worn so we have ordered a replacement which we will get installed as soon as we can. This will require the old one to be dug out along with its concrete foundation and the new one replacing in new concrete. The roundabout will then be reinstalled with new bearings.
- The spring snapped on the springy elephant, so this has been removed until we have a replacement spring fitted.
- The handles have been replaced on the overhead spinner (a shackle needed replacement).
- The seesaw was removed for safety reasons, and we are trying to source a supplier for the replacement parts.

It is unfortunate that all these things have happened at the same time, and we are experiencing some delays when ordering replacement parts. Notwithstanding this, we will try and install the repaired/replacement equipment as soon as possible.

Kind regards
Paul